





Nadeln

12 in einer Dose





1/2 Kreis



| |  | |  | |
|------------|---|--------------------|---|---------------------|
| | Ohne Federöhr GN | Mit Federöhr GF | Ohne Federöhr GRN | Mit Federöhr GRF |
| 90 mm N°00 | | Z 751 | | Z 850 |
| 80 mm N°1 | Z 702 | Z 752 | | Z 851 |
| 70 mm N°2 | Z 703 | Z 753 | | Z 853 |
| 65 mm N°3 | Z 704 | | | |
| 60 mm N°4 | | Z 755 | | Z 855 |
| 55 mm N°6 | Z 706 | Z 756 | Z 806 | Z 856 |
| 50 mm N°7 | | Z 758 | Z 807 | Z 858 |
| 48 mm | | | | Z 840 |
| 45 mm N°8 | Z 708 | Z 759 | Z 808 | Z 859 |
| 40 mm N°9 | Z 710 | Z 760 | Z 810 | Z 860 |
| 35 mm N°10 | Z 711 | Z 761 | Z 811 | Z 861 |
| 30 mm N°12 | Z 712 | Z 762 | Z 812 | Z 862 |
| 25 mm N°13 | Z 713 | Z 763 | Z 813 | Z 863 |
| 20 mm N°15 | Z 714 | Z 764 | Z 814 | Z 864 |
| 16 mm N°16 | | Z 766 | | Z 866 |


HALBGEBOGENE NADELN (SKI)



| |  | |
|------------|---|--------------|
| | Ohne Federöhr | Mit Federöhr |
| 80 mm N°1 | Z 202 | |
| 70 mm N°2 | Z 203 | |
| 65 mm N°3 | Z 204 | |
| 60 mm N°4 | Z 205 | |
| 57 mm N°5 | Z 201 | |
| 55 mm N°6 | Z 206 | |
| 50 mm N°7 | Z 207 | |
| 45 mm N°8 | Z 208 | |
| 40 mm N°9 | | Z 260 |
| 35 mm N°10 | | Z 261 |
| 30 mm N°12 | | Z 262 |
| 25 mm N°13 | | Z 263 |
| 20 mm N°15 | | Z 264 |
| 16 mm N°16 | | Z 266 |
| 12 mm N°20 | | Z 268 |



3/8 Kreis


| | Ohne Federöhr BN | Mit Federöhr BF | Ohne Federöhr BRN | Mit Federöhr BRF | Ohne Federöhr BRT |
|------------------|---------------------|--------------------|----------------------|---------------------|----------------------|
| 130 mm N°6-0 | Z 495 | | Z 595 | | |
| 110 mm N°4-0 | | | Z 599 | | |
| 100 mm N°000 | Z 500 | Z 550 | | Z 650 | |
| 90 mm N°00 | Z 501 | Z 551 | Z 601 | Z 651 | Z 301 |
| 90 mm LIGHT N°00 | Z 502 | | Z 602 | | |
| 85 mm N°0 | | | Z 590 | | |
| 80 mm N°1 | Z 503 | Z 552 | Z 591 | Z 652 | Z 303 |
| 70 mm N°2 | Z 504 | Z 553 | Z 603 | Z 653 | |
| 70 mm LIGHT N°2 | Z 504L | | | | |
| 65 mm N°3 | | Z 554 | Z 604 | | |
| 60 mm N°4 | Z 505 | Z 555 | | Z 655 | |
| 57 mm N°5 | Z 506 | | Z 605 | | |
| 55 mm N°6 | | Z 556 | | Z 656 | |
| 50 mm N°7 | | Z 557 | Z 607 | Z 657 | |
| 45 mm N°8 | Z 508 | Z 558 | Z 608 | Z 658 | |
| 40 mm N°9 | Z 510 | Z 560 | Z 610 | Z 660 | |
| 35 mm N°10 | Z 511 | Z 561 | Z 611 | Z 661 | |
| 32 mm N°11 | | Z 570 | | Z 670 | |
| 30 mm N°12 | Z 512 | Z 562 | Z 612 | Z 662 | |
| 25 mm N°13 | Z 513 | Z 563 | Z 613 | Z 663 | |
| 22 mm N°14 | | Z 571 | | Z 671 | |
| 20 mm N°15 | Z 514 | Z 564 | Z 614 | Z 664 | |
| 16 mm N°16 | Z 516 | Z 566 | | Z 666 | |
| 14 mm N°17 | | Z 567 | | Z 667 | |
| 12 mm N°20 | | Z 568 | | | |


GERADE

Ohne Federöhr GSN Mit Federöhr GSF


| | | |
|-------------|-------|-------|
| 75 mm N° 1 | | Z 904 |
| 60 mm N° 4 | Z 903 | Z 913 |
| 45 mm N° 8 | Z 902 | |
| 40 mm N° 9 | | Z 912 |
| 35 mm N° 10 | | Z 911 |


S-FÖRMIG GEBOGENE NADELN

Ohne Federöhr GSN


| | |
|--------|-------|
| 110 mm | Z 403 |
| 135 mm | Z 401 |
| 145 mm | Z 402 |